ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone DASARAHALLI	**Ward No.** 13	**Ward Name** Mallasandra
Street ID W0217, W0213, W0215, W0224, W0192	**Street Name** NA	**Significant Landmark** Ganesha Temple
Segment No. 13/C-W0217/S031506	**Total Length (m)** 450.97	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	172.31	77.517387	13.049902	77.518127	13.051279	Pipe Line Road	1st Cross Ravindra Nagara
2	62.39	77.517425	13.050590	77.517945	13.050349	6th Cross Santhosh Nagara	8th Cross Santhosh Nagara
3	216.27	77.517462	13.049304	77.518347	13.051055	Pipeline Road	1st Cross Ravindra Nagara

Work Details

History of Road / Lane / Circles

Name of the Work
Improvments And Asphalting At 6th 7th And Other Roads Santhosh Nagara In Mallasandra Ward No 13 Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2018

Year
2018 - 2019

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details

Job No. / Work Code
013-18-000101

Work Order No.
BBMP/EE/DD/WO/364/18-19

Work Order Date
27/02/2019

Period of Extention

Defect Liability Period From
21/03/2019

Defect Liability Period To
21/03/2020

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0217, W0213, W0215, W0224,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ಮಲ್ಲಸಂದ್ರ, ಬೆಂಗಳೂರು

Scanned by CamScanner